

4. CUT OUT INNER LEGS ALONG TRIM LINE AND GLUE TO INSIDE LEG OF MAIN BODY

5. SEPARATE LEGS PER THE DRAWING

WHEEL HVBS- FOLD AND GLVE, THEN CVT TO SHAPE

